

## BCM

# **Product Change Notice**


PCN Type: ■HW/SYS/Kit □BIOS/LAN/FW □Package/Label □Driver/OS □Acc. □Others Page: <u>1</u> of <u>2</u>								
PCN Number: P250301		Revision: B		Date of Publication: January 13, 2025				
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW REVISION TYPE		REVISION TYPE				
ECM-RPLP-65U	71991	1.0	1.1	Hardware				
ECM-RPLP-15U	71993	1.0	1.1					
ECM-RPLP-35U	71997	1.0	1.1					
KIT-ECM-RPLP-65U-B	69556	1.0	1.1	Kit				
A68-A1								

#### REASON OF CHANGE:

Heat sink is too close to the BIOS socket and may cause interference.

### DESCRIPTION OF CHANGE:

Adjust the heatsink to add 1.5mm height clearance over the BIOS socket.



#### IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure no quality, reliability, functional, or thermal implications.

BCM is not recommending our customers to perform additional qualification of this change.

AFFECTED BY THIS CHANGE				
Specification	NO			
Packaging	NO			
Labeling	NO			
BIOS	NO			
Driver	NO			
Hardware/ Kit	YES			

CUT IN DATE:

Date: July 21, 2025 OR

Lot#:

\*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	Х		
In Process		Х	
Finished Goods		Х	
RMA		Х	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on December 23, 2024. This PCN had been **APPROVED** by BCM Procurement Department on January, 2025.

#### **APPROVED BY**

CUSTOMER	<approved></approved>	January 13, 2025
Signature		Date