BCM

Product Change Notice

PCN Type: ■HW/SYS/Kit ■BIOS/LAN/FW □Package/Label □Driver/OS □Acc. □Others   Page: _1_ of _1_

PCN Number: P222801		Revision: A	Date of Publication: 07/13/2022	
PRODUCT NAME	**PRODUCT PART#**	OLD — REV. — NEW		**REVISION TYPE**
ECM-3455J	71811-IA	1.0	1.1	Hardware
		1.00	1.10	BIOS

REASON OF CHANGE:

Current Infineon SLB9665TT2.0 Trust Module Platform (TPM) is constrained creating extended manufacturing lead times

DESCRIPTION OF CHANGE:

Change to use Intel Platform Trust Technology (TCG TPM 2.0).

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability or thermal implications to our customer.

BCM is not recommending our customer to perform additional qualification of this changes, except customer is using TPM function.

AFFECTED BY THIS CHANGE	
Specification	YES
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	YES

CUT IN DATE:

Date: October, 2022
   OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on July, 2022.
This PCN had been **APPROVED** by BCM Procurement Department on July, 2022.

APPROVED BY

VP OF SALES	<APPROVED>	07/13/2022
	Signature	**Date**