BCM

Product Change Notice

PCN Number: 71521-B1-005		Revision: A		Date of Publication: 05/29/2019	
PRODUCT NAME	**PRODUCT PART#**	OLD **— REV. —** NEW		**REVISION TYPE**	
MX3350N	71521-IA	2.20	2.30	BIOS	

REASON OF CHANGE:

1) Apply Intel Quarterly Security Release (QSR) 2018.2, 2018.4 and 2019.1.
2) Address Installing / Uninstalling Intel Trusted Execution Engine (TXE™) driver not working properly issue.
3) Minor bug fix related to TXE Software, Tools and Firmware (FW).

DESCRIPTION OF CHANGE:

1) Update TXE FW version to 3.1.65.2318.
2) Update TXE Driver version to 3.1.65.2318.

File name: 71521230.BIN
Message: MX3350N 71521 BIOS V2.30
Version#: 2.30
File date/ time: 05/08/2019 1:43:40 AM
Checksum: CE90 hex
Programming Method: Using AMI Firmware Update Utility v5.07.00 (EFUx64.EFI) under EFI.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal and regulation implications to our customer.

BCM is recommending our customers to perform additional qualification of this changes only if the previous version of TXE Driver was being used on their deploy Operation System image.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	YES
Hardware	NO

CUT IN DATE:

Date: July, 2019
  OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process	X		
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 05/20/2019.
This PCN had been **APPROVED** by BCM Procurement Department on May, 2019.

APPROVED BY

VP OF SALES	<APPROVED>	05/29/2019
	Signature	**Date**