



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 71142-B1-006		Revision: A		Date of Publication: 05/28/2019
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW	REVISION TYPE	
MX3160N	71142-IA	2.01	2.04	BIOS

REASON OF CHANGE:

- 1) Resolve system hanging issue when connecting a display device to the secondary display connection with no display connected to the primary display connection.
- 2) Add DP2/ LVDS + DP1 boot display options.
- 3) Improve Mini-PCIe WiFi card compatibility issue.

DESCRIPTION OF CHANGE:

File name: 71142204.ROM
 Message: MX3160N #71142 BIOS V2.04
 Version#: 2.04
 File date/ time: 01/02/2019 12:24:26 PM
 Checksum: F2FF hex
 Programming Method: AMI Firmware Update Utility v5.07.01 (afudos.exe)

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal and regulation implications to our customer.
 BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	YES
Driver	NO
Hardware	NO

CUT IN DATE:

Date: 07/02/2019
 OR
 Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 01/02/2019.
 This PCN had been **APPROVED** by BCM Procurement Department on May, 2019.

APPROVED BY

VP OF SALES	<APPROVED>	05/28/2019
--------------------	------------	------------

Signature

Date