



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: H174401		Revision: A		Date of Publication: 10/27/2017
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX3160N	71142-IA	1.0A	2.0	Hardware
		1.02	2.00	BIOS

REASON OF CHANGE:

- 1) To address the Intel® Celeron® Processor N3160 LPC issue.
- 2) To address TPM security issue.
- 3) To meet the latest air freight product labeling regulations.

DESCRIPTION OF CHANGE:

- 1) Add LPC bus level circuit
- 2) Update TPM FW to 5.62.
- 3) Add UN3091 labels on the box outside.
- 4) Update the BIOS to revision 2.00.

IMPACT OF CHANGE AND RECOMMEND ACTION:

This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or thermal implications to our customers.

BCM is not recommending our customers to perform additional qualification of this changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	YES
BIOS	YES
Driver	NO
Hardware	YES

CUT IN DATE:

Date: Jan, 2018
OR
Lot#:

*Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 10/27/2017.

APPROVED BY

VP OF SALES	<APPROVED>	10/27/2017
--------------------	------------	------------

Signature

Date