

# **Product End of Life (EOL) Notification**

## Change Notification #: E1535251

### Change Title: BCM® MX67QM & BI355-67QM Official End of Life Notice

Date of Publication: 08/25/2015

#### Key Characteristics of the Change:

Product is being discontinued due to lifecycle and diminished demand.

#### **Customer Impact of Change and Recommended Action:**

- 1. BCM is accepting last time buy orders through February 25, 2016 for the MX67QM and BI355-67QM.
- 2. At BCM's discretion, last time by orders may be scheduled to ship through August 25, 2016 with a non-cancellable and non-returnable (NCNR) PO.
- 3. For NCNR orders BCM may require an advanced deposit covering material costs.

#### Products Affected / BCM Ordering Codes: MX67QM (71321-C); BI355-67QM (69034)

#### Recommended Replacement Products: MX81H, MX87QD, MX110H, MX170QD, BI360-81H

### Reference Documents / Attachments: N/A

Information in this document is provided in connection with BCM products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document.

Except as provided in BCM's Terms and Conditions of Sale for such products, BCM assumes no liability whatsoever, and BCM disclaims any express or implied warranty, relating to sale and/or use of BCM products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. BCM may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the BCM Representative(s) Copyright © BCM Corporation 2008. Other names and brands may be claimed as the property of others.