



Product Change Notice

PCN Type: Ha	dware □BIOS/Firmwa	are ⊡Package	e/Label □	Driver □O	thers Page: <u>1</u> of <u>1</u>	
PCN Number: 71321-H1-002		Revision: A		Date of	Date of Publication: 07/11/2012	
PRODUCT NAM	E PRODUCT PART#	OLD — REV. — NEW			REVISION TYPE	
MX67QM	71321-C	1.0A	1.1	Hardwa	re	
REASON OF CHA	NGE:					
Change COM port	default voltage to 5V.					
DESCRIPTION O	CHANGE:					
Add jumper cap ar	nd position for 5V as det	fault.				
IMPACT OF CHA	NGE AND RECOMMEN	ID ACTION:				
implications to ou BCM is not recom	r customers.				, reliability, functional or driver ese changes.	
AFFECTED BY						
Specification	NO					
Packaging	NO					
Labeling	NO					
BIOS	NO					
Driver	NO					
Hardware	YES					
CUT IN DATE: Date: 09/21/2012 OR Lot#: *Cut in date is bas	ed on the current foreca	st				
Parts Dispositio	n Rework	As Is		Scrap		
New Order		X				
In Process		X				
Finished Goods		Х				
RMA		X				
This PCN had bee	n QUALIFIED and APP	ROVED by BC	M Enginee	ring Departr	nent on 07/11/2012.	
APPROVED BY						
CUSTOMER/ VP OF SALES	<approved></approved>	07/11/2	012			

Signature

Date