



BCM

Product Change Notice

PCN Type: HW/SYS/Kit BIOS/LAN/FW Package/Label Driver/OS Acc. Others Page: 1 of 1

PCN Number: 70932-L1-002		Revision: A		Date of Publication: 11/13/2017
PRODUCT NAME	PRODUCT PART#	OLD — REV. — NEW		REVISION TYPE
MX87QD	70932-C	1.00	1.01	LAN1 (i217-LM) Image

REASON OF CHANGE:
 Fixed security vulnerability to cause Intel DAL failures, breaking Intel Identity Protection Technology and True key functionalities. (Documented in Intel CVE-2017-5689).

DESCRIPTION OF CHANGE:
 Update LAN1 Image to 1.01.

IMPACT OF CHANGE AND RECOMMEND ACTION:
 This change has been thoroughly evaluated to ensure that there is no quality, reliability, functional, thermal or regulation implications to our customers.
 BCM is not recommending our customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
Firmware	YES
Driver	NO
Hardware	NO

CUT IN DATE:
Date: Nov, 2017
 OR
Lot#:
 *Cut in date is based on the current forecast.

Parts Disposition	Rework	As Is	Scrap
New Order	X		
In Process		X	
Finished Goods		X	
RMA		X	

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 11/13/2017.

APPROVED BY

VP OF SALES	<APPROVED>	11/13/2017
--------------------	------------	------------

Signature

Date