



## **Product Change Notice**

PCN Number: P244701		Revision: A		Date of Publication: 11/20/2024	
PRODUCT NAME	PRODUCT PART#	OLD - RE	<b>V. —</b> NEW		REVISION TYPE
BC680R	71832-IA	1.60	1.70	BIOS	
REASON OF CHANG	GE:	·			
Addressing the poter	itial crash problem wi	ith Intel 13 <sup>th</sup> an	d 14 <sup>th</sup> Genera	ation processors	
DESCRIPTION OF C					
DESCRIPTION OF C	HANGE:				
Update Intel Microco	de to Ov12B				
File name: 71832170	ROM				
Message: BC680R (71					
	5/2024 10:11:29 AM				
File size: 16,777,216	-				
Checksum: AAC4 hex	•				
Programming metho	d. Use AMI Firmware	Update Utility	(AfuEfix64.ef	i) under UEFI	
		0,0000	(		
0					
IMPACT OF CHANG	E AND RECOMMEN	D ACTION:			
IMPACT OF CHANG This change has beer	E AND RECOMMEN thoroughly evaluate	<b>D ACTION:</b> d to ensure that	at there are n	•	onal, or compliance implications
IMPACT OF CHANG This change has beer	E AND RECOMMEN thoroughly evaluate	<b>D ACTION:</b> d to ensure that	at there are n	•	onal, or compliance implications cation of this change.
IMPACT OF CHANG This change has beer for our customers. B(	E AND RECOMMEN thoroughly evaluate CM is not recommend	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has beer for our customers. Bo AFFECTED BY THI	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. B( AFFECTED BY THI Specification	E AND RECOMMEN thoroughly evaluate CM is not recomment S CHANGE NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has beer for our customers. B( AFFECTED BY THI Specification Packaging	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. B( AFFECTED BY THI Specification Packaging Labeling BIOS	E AND RECOMMEN thoroughly evaluate CM is not recomment S CHANGE NO NO NO YES	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG         This change has been         for our customers. Bo         AFFECTED BY THI         Specification         Packaging         Labeling         BIOS         Driver	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO NO YES NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware	E AND RECOMMEN thoroughly evaluate CM is not recomment S CHANGE NO NO NO YES	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO NO YES NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. B( AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE:	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. B( AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE:	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 20 OR	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO	<b>D ACTION:</b> d to ensure that	at there are n	•	
IMPACT OF CHANG         This change has been         for our customers. Bo         AFFECTED BY THI         Specification         Packaging         Labeling         BIOS         Driver         Hardware         CUT IN DATE:         Date: December 1, 20         OR         Lot#:	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO NO YES NO NO NO	D ACTION: d to ensure that ding customers	at there are n	•	
IMPACT OF CHANG         This change has been         for our customers. Bo         AFFECTED BY THI         Specification         Packaging         Labeling         BIOS         Driver         Hardware         CUT IN DATE:         Date: December 1, 20         OR         Lot#:	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO	D ACTION: d to ensure that ding customers	at there are n	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 20 OR Lot#:	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO NO YES NO NO NO	D ACTION: d to ensure that ding customers	at there are n to perform a	idditional qualifi	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 20 OR Lot#: *Cut in date is based	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO NO 225 on the current foreca	D ACTION: d to ensure that ding customers	at there are n to perform a	•	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 20 OR Lot#: *Cut in date is based Parts Disposition	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO 225 on the current foreca Rework	D ACTION: d to ensure that ding customers	at there are n to perform a	idditional qualifi	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 20 OR Lot#: *Cut in date is based Parts Disposition New Order	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO 225 on the current foreca Rework	D ACTION: Ind to ensure that ding customers st. As Is	at there are n to perform a	idditional qualifi	
IMPACT OF CHANG This change has been for our customers. Bo AFFECTED BY THI Specification Packaging Labeling BIOS Driver Hardware CUT IN DATE: Date: December 1, 2 OR Lot#: *Cut in date is based Parts Disposition New Order In Process	E AND RECOMMEN thoroughly evaluate CM is not recommend S CHANGE NO NO YES NO NO 225 on the current foreca Rework	D ACTION: d to ensure that ding customers st. As Is X	at there are n to perform a	idditional qualifi	• • •

VP OF SALES	<approved></approved>	November 20, 2024
Signature		Date

Doc#: F-G0-0-007A