



# BCM

## Product Release Notice

PRN Type:  Hardware  BIOS/Firmware  Test  Driver  Others Page: 1 of 1

<b>PRN Number:</b> 71251-H1-001		<b>Revision:</b> A		<b>Date of Publication:</b> 08/09/2010
<b>PRODUCT NAME</b>	<b>PRODUCT PART#</b>	OLD — REV. — NEW	<b>REVISION TYPE</b>	
MX45GM2	71251-C	0.1	1.0	Hardware Revision

**REASON OF CHANGE:**  
Production Release

**DESCRIPTION OF CHANGE:**  
Change from 8.6mm to 5.6mm CF Socket.



**IMPACT OF CHANGE AND RECOMMEND ACTION:**  
This change has been thoroughly evaluated to ensure that there are no quality, reliability, functional or driver implications to our customers.  
BCM is not recommending customers to perform additional qualification of these changes.

AFFECTED BY THIS CHANGE	
Specification	NO
Packaging	NO
Labeling	NO
BIOS	NO
Driver	NO
Hardware	YES

**CUT IN DATE:**  
Date: 09/10/2010  
OR  
Lot#:  
\*Cut in date is based on the current forecast.

This PCN had been **QUALIFIED** and **APPROVED** by BCM Engineering Department on 08/04/2010.

**APPROVED BY**

<b>CUSTOMER/ VP OF SALES</b>	<APPROVED>	08/09/2010
----------------------------------	------------	------------

Signature

Date