



Product Change Notice

	PCN Number: P223901			Date of Publication: 09/26/2022	
PRODUCT NAME	PRODUCT PART#	Revision: B OLD — REV. — NEW		REVISION TYPE	
RX370Q	70601-IA	1.2	1.3	Hardware	
REASON OF CHANC	SE:				
ntel I211AT Ethernet	controller will be En	d of Life.			
DESCRIPTION OF C	HANGE:				
Change to use Intel 12	10AT Ethernet contro	oller.			
MPACT OF CHANG	E AND RECOMMEN	D ACTION:			
This change has been customer.	thoroughly evaluate	d to ensure that th	nere are r	no quality or reliability implications to ou	ur
Windows 10 or 11 dri	vers.	erform additional c	qualificati	ion of these changes, unless using Micro	soft
AFFECTED BY THI					
Specification	YES				
Packaging Labeling	NO				
BIOS	NO NO				
	NU				
Driver	YES				
Driver Hardware	YES YES 23	st.			
Driver Hardware CUT IN DATE: Date: September, 202 OR Lot#: Cut in date is based	YES YES 23 on the current foreca			Scran	
Driver Hardware CUT IN DATE: Date: September, 202 OR Lot#: *Cut in date is based Parts Disposition	YES YES 23 on the current foreca Rework	st. As Is		Scrap	
Driver Hardware CUT IN DATE: Date: September, 202 OR _ot#: Cut in date is based Parts Disposition New Order	YES YES 23 on the current foreca	As Is		Scrap	
Driver Hardware CUT IN DATE: Date: September, 202 OR Lot#: Cut in date is based Parts Disposition New Order In Process	YES YES 23 on the current foreca Rework	As Is X		Scrap	
Driver Hardware CUT IN DATE: Date: September, 202 OR _ot#: Cut in date is based Parts Disposition New Order	YES YES 23 on the current foreca Rework	As Is		Scrap	

APPROVED BY

VP OF SALES	<approved></approved>	09/26/2022
-------------	-----------------------	------------